

Administrator:
Ms Letícia Szűcs

Date:
31 03 2023

TEST REPORT NUMBER: 3/169-2023(E)

Client: K9 Sport Kft.
Address: Hungary 6310 Szigetszentmiklós, Ipar u. 10-12.
Contact person Mr. Tamás Pióker
Number of Order: -
Date of Order: 28 03 2023
Receipt of Order: 28 03 2023
Tested sample: IDC power harness with plastic accessories*
Size: S*
Sampling: Sampling was performed by the Client.
Date of arrival of sample: 28 03 2023
Date of testing: 28 03 2023
Atmosphere used for testing: Temperature: 20 ± 2°C.
Relative humidity: 65 ± 4%.
Test performed: Tensile test.

**Data of the sample given by the Client.*

This report must only be reproduced in full and not in extract form.

TEST RESULTS

Tensile test. Evaluation according to MSZ EN ISO 13934-1:2013.

Number of test specimens: 5.

Rate of extension: 100 mm/min. Type of device used: INSTRON 3369.

Clamping of specimen: the artificial dog mannequin was fastened on the lower clamping, the harness on the artificial dog mannequin was fixed to the cross head.

Tested parameter	1.	2.	3.	4.	5.	Average
Breaking strength (N)	1596*	1666*	1581*	1635**	1626*	1621

*The plastic ring was broken.

**The velcro was opened.

- Notes:
- The test results relate only to the tested sample.
 - The testing laboratory is not liable for the data given by the client and for the possible effects on the result caused by data given and the sampling performed by the Client.
 - This Test Report contains 2 pages, which can only be copied in full unless the written permission of the testing laboratory is obtained.

The tested sample:

- was destroyed through the test
- the rest of it (signed) is going to be sent to the Client as per request
- the rest of it will be stored for at least 3 months after issuing the test report, and will be destroyed afterwards
- Validity of the electronically issued test report (pdf) is proven by digital signature
- Status of the testing laboratory: Laboratory accredited by NAH under No NAH-1-1366/2021.

Ágnes Kovács
Head of Testing Department